

US EPA ARCHIVE DOCUMENT

# Situation Photo Log

Monday, February 4, 2013

Kalamazoo River / Enbridge Spill

## Water / Sediment Temperatures

Location	Water Temp. (°F)	Sediment Temp. (°F)
C0.4 Water Gauge	N/A*	N/A*
C3.2 Water Gauge	N/A*	N/A*
E0.5 Water Gauge	N/A*	N/A*
E2 Water Gauge	N/A*	N/A*
E4 Water Gauge	N/A*	N/A*

\*Water/Sediment Temperatures were unable to be collected due to ice formation along the river bank.

Prepared by:  
Karen Berecz  
START-USEPA  
Situation Unit



**1. Confluence observed icing conditions.**



**2. MP2.25 observed river icing conditions.**



3. C0.4 Boat Launch observed upstream river icing conditions.



4. C0.4 Boat Launch observed downstream river icing conditions.





**5. Ceresco Dam impoundment observed upstream river icing conditions.**



**6. Ceresco Dam impoundment observed downstream river icing conditions.**



7. Ceresco Dam observed icing conditions.



8. C3.2 Pole Barn observed core logging procedures.





**9. C3.2 Boat Launch observed upstream river icing conditions.**



**10. C3.2 Boat Launch observed downstream river icing conditions.**





11. MP13.50 RDB observed the RI team.



12. MP13.50 observed river icing conditions.





**13. MP15.25 South Mill Pond observed river icing conditions.**



**14. MP15.25 South Mill Pond observed back water icing conditions.**



15. MP15.50 North Mill Pond observed river icing conditions.



16. MP15.50 North Mill Pond observed back water icing conditions.





17. MP21.50 observed river icing conditions.



18. MP21.50 Oxbow observed icing conditions.





**19. MP27.00 Shady Bend Campground observed river icing conditions.**



**20. E2 Boat Launch observed river icing conditions.**





**21. Morrow Lake Delta observed icing conditions.**



**22. Morrow Lake Delta observed icing conditions.**



**23. Morrow Lake Neck/Morrow Lake Delta observed icing conditions.**



**24. Morrow Lake observed icing conditions.**